BOATYARD GENERAL PERMIT

BOATYARD GENERAL PERMIT

- PERMIT BACKGROUND
- WHAT'S REQUIRED
- WHAT'S DIFFERENT FROM PREVIOUS PERMIT?
- HOW DOES THIS PERMIT COMPARE
- WHAT HAPPENS WITH EXCEEDENCE OF LIMITS OR BENCHMARKS

BACKGROUND

- FIRST PERMIT IN 1992 ONE OF THE FIRST STORMWATER PERMITS
- •DISCHARGE PERMITS ARE REQUIRED BY FEDERAL AND STATE LAW
- DISCHARGE PERMITS REQUIRE PERMITTEES TO DO TWO FUNDAMENTAL THINGS:
 - 1. TREAT WASTEWATER WITH ALL KNOWN, AVAILABLE, AND REASONABLE METHODS OF TREATMENT
 - 2. MEET THE STATE'S WATER QUALITY STANDARDS

BACKGROUND

- CURRENT PERMIT ISSUED IN NOVEMBER 2005
- PERMIT APPEALED DECISION?

LIMITS ON METAL CONCENTRATIONS FOR PRESSURE WASH WATER GOING TO A MUNICIPAL TREATMENT PLANT (BASED ON SEATTLE'S LIMITS FOR THEIR TREATMENT PLANTS)

MEET LIMIT OR BENCHMARK CONCENTRATIONS OF COPPER, SOLIDS AND OIL/GREASE IN STORMWATER RUNOFF

<u>LIMIT</u> = EACH EXCEEDENCE SUBJECT TO PENALTY BY ECOLOGY OR CITIZEN

<u>BENCHMARK</u> = INDICATOR OF BMP EFFORT OR WATER QUALITY IMPACT – USUALLY A PROCESS ASSOCIATED WITH EXCEEDENCE

OIL/GREASE – 6.0 mg/l BENCHMARK BASED ON BEST 50TH PERCENTILE FACILITIES PERFORMANCE

TOTAL SUSPENDED SOLIDS – 21.0 mg/l BENCHMARK BASED ON BEST 50TH PERCENTILE FACILITIES PERFORMANCE

COPPER:

DISCHARGE TO GROUND – 1000 μ g/L LIMIT DISCHARGE TO LAKE (SHIP CANAL) – 38 μ g/L BENCHMARK

COPPER:

DISCHARGE TO RIVER – 384 μg/L BENCHMARK

DISCHARGE TO MARINE WATER – 229 μg/L BENCHMARK

COPPER BENCHMARK (AS TOTAL) CALCULATED AS:
WQ CRITERIA X 1/%DISSOLVED X DILUTION FACTOR X
RECEIVING WATER EFFECT

BEST MANAGEMENT PRACTICES (BMPs) AS REQUIRED TO CONTROL POLLUTANT CONCENTRATION IN STORMWATER RUNOFF

DOCUMENT CONTROL EFFORTS IN A STORMWATER POLLUTION PREVENTION PLAN

SAMPLE AND ANALYZE STORMWATER RUNOFF IN SEPTEMBER, OCTOBER, JANUARY, APRIL AND MAY

REPORT SAMPLE RESULTS TO ECOLOGY WITH ADDITIONAL CONTROL EFFORTS IF REQUIRED

WHAT'S DIFFERENT FROM PREVIOUS PERMIT

MONITORING FREQUENCY FOR PRESSURE WASH WATER FROM 3 TO 4 TIMES/YEAR

ADDITIONAL NARRATIVE REQUIREMENTS FOR PRESSURE WASH WATER GOING TO A MUNICIPAL TREATMENT PLANT

NEW MANDATORY BMP - VACUUM SANDING AND GRINDING

BENCHMARKS AND <u>LIMITS</u> ON COPPER, TSS AND OIL/GREASE

WHAT'S DIFFERENT FROM PREVIOUS PERMIT

REQUIREMENT TO DOCUMENT POLLUTION CONTROL EFFORTS IN A STORMWATER POLLUTION PREVENTION PLAN

INSPECTIONS – 1/WEEK
INSPECTION CHECKLIST FROM ECOLOGY

ADDITIONAL SAMPLING MONTH - JANUARY

NO FOLLOW-UP SAMPLING FOR MISSED MONTH

HOW DOES OUR PERMIT COMPARE?

CALIFORNIA

1. The acute toxicity of storm water runoff to surface waters or to storm drains shall not be less than seventy (70) percent survival as determined by a 96-hour bioassay based on a grab sample.

USEPA AND OREGON – MULTI-SECTOR GENERAL PERMIT

- VISUAL MONITORING AND SWPPP

WASHINGTON INDUSTRIAL GENERAL STORMWATER PERMIT (benchmark/action level)

COPPER 63.6/149 OIL/GREASE 15/30

HOW DOES OUR PERMIT COMPARE?

USEPA – MULTI-SECTOR GENERAL PERMIT (CURRENT DRAFT) FOR SHIPYARDS AND BOATYARDS CATEGORIES

TSS BENCHMARK – 100 mg/l and SWPPP

WHAT HAPPENS IF LIMITS AND BENCHMARKS ARE EXCEEDED?

EXCEEDANCE OF ANY LIMIT = PERMIT VIOLATION

EXCEEDANCE OF A BENCHMARK

1ST, 2ND, AND 3RD (LEVEL 1) – REPORT TO US ON CORRECTIVE ACTION AND COMPLETE ENHANCED OR ADDITIONAL BMPs

- DEVELOP BMP PLAN AND PLACE IN SWPPP
- IMPLEMENT WITH 2 WEEKS (NON-CAPITAL) OR 6 MONTHS (CAPITAL)

WHAT HAPPENS IF LIMITS AND BENCHMARKS ARE EXCEEDED?

- 4TH START INVESTIGATING TREATMENT OPTIONS
 - REPORT TO US (separate report)

6TH – ENGINEERING REPORT

ECOLOGY CONTACTS

INSPECTORS

SOUTHWEST REGIONAL OFFICE

LYDIA CABEZA WAGNER (LBLA461@ECY.WA.GOV)

Tel. 360 407-6291

NORTHWEST REGIONAL OFFICE

CINDY CALLAHAN (CYCY461@ECY.WA.GOV)

Tel. 425 649-7059

BELLINGHAM FIELD OFFICE

ANDREW CRAIG (ACRA461@ECY.WA.GOV)

Tel. 360 676-2217

Directory - www.ecy.wa.gov/org.html



DIRECTORY

Please note: Use of this directory for commercial purposes is prohibited (Chapter 42.17 Revised Code of Washington).

Staff Telephone/E-Mail
Directory (PDF version 0.6 MB)

Staff Contacts by Subject (PDF version 1.1 MB)

Organization Chart (PDF file)

Offices (includes addresses, local maps, phone numbers, and key staff):

- Headquarters (includes Manchester Laboratory and Quality Assurance) (Statewide)
- Northwest Regional Office / Bellingham Field Office / Puget Sound Field Office (Island, King, Kitsap, San Juan, Skagit, Snohomish, and Whatcom counties)
- Southwest Regional Office / Vancouver Field Office
 (Clallam, Clark, Cowlitz, Grays Harbor, Jefferson, Mason, Lewis, Pacific, Pierce, Skamania, Thurston, and Wahkiakum counties)
- <u>Central Regional Office / Methow Valley Field Office</u>
 (Benton, Chelan, Douglas, Kittitas, Klickitat, Okanogan, and Yakima counties)
- Eastern Regional Office / Colville Field Office / Ephrata Field Office / Walla Walla Field Office (Adams, Asotin, Columbia, Ferry, Franklin, Garfield, Grant, Lincoln, Pend Oreille, Spokane, Stevens, Walla Walla, and Whitman counties)
- <u>Padilla Bay National Estuarine Research Reserve / Breazeale Interpretive Center</u>
- Richland Field Office (nuclear waste issues only)